PRICE & MYERS

Job No.	27259	Page		Rev	1
Date	07/07/22	Eng	IS	Chd	IS
Job	Artwork Logistics- Torsion				

Survey requirements

First 5 layers

Approximate outline of pieces



Model to show clear space throughout sculpture when assembled



Position of all metal plate positions and thicknesses

Location of bolts required



Position of all metal plate positions and thicknesses

Required output- 3d CAD drawing of assembled sculpture even if parts need to be documented individually

Accuracy to be +/- 2mm